FIELD INSPECTION REPORT

Date of Inspection: 0	2/12/2020	District: PULMER
Division: purner		Length (km): 3.00 KM
Name of the Road: Co	- ophetive Baza	& Svimagel to reakting has
Scheme/Programme:	MAINTENANCE	0
Package No.:		Read Id No.:
Status of the Project:	Ongoing/Completed	Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance	

SL No.	Parameters to be checked	Remarks
1.	Pavement	,
a)	Road Junction condition	š⁄ų
b)	Condition of Surfacing	
c)	Riding Quality	
d)	Road Camber	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	
c)	Condition of railings/slab/approach for Bridges	-S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating

Satisfactory (S) Satisfactory but requires Improvement (SRI) Unsatisfactory (U)

NAME: Chandan Kumar Bladgar

DESIGNATION: Assistant Engineed

Rusal Works Division purner

Scanned with CamScanner

Scanned with CamScanner