FIELD INSPECTION REPORT

Date of I	nspection:	2/12/2020	District: le cumur	
Division		tani 9	Length (km): 6 30	
Name of	the Road:	NH2 to Mar	mary vill vig puso	uli Cumit
Scheme/l	Programme:	MAINTENANCE		1 1 1
Package			Road Id No.:	
	the Project:	Ongoing/Completed	/Under Maintenance	
Work is	a case of:		Jp gradation/ Maintenance	Remarks
Sl. No.	Parameters to be checked Remarks			
1.	Pavement		4-4-4-1-3-2-1-3-2-1-6-6-6-6-6-6-6-6-6-6-6-6-6-6-6-6-6-6	
a)	Road Junction condition			S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality			√S/U
d)	Road Camber			√S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Ves/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			✓s/sri/u
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			√s/sri/u
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3,	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4.	Compliance	History		
a)	Status of ATR's & any others			No
Quarall	Pating			
		Satisfactory (S)		'S'
	4 1		requires Improvement (SRI)	
		Unsatisfactory (U)	