FIELD INSPECTION REPORT

Date	of Inspection:	2-12-2020	District: Caya		
Division: TIKARI Length (kn Name of the Road: Bela base bay wash main Scheme/Programme: MAINTENANCE				k M	
Name	of the Road: Ba	la barabar su	and main sound	tuchala	-am law
				3.014	
Status	ge No.: Bela b of the Project:		Road Id No.:		
Work is a case of:		Now Complete	d/Under Maintenance		1
SI. No.		to a section of the s	Up gradation/ Maintenance	3	
1.	Pavement	Parameters to	be checked		Remarks
a)					
-	Road Junction condition				S/U
b)	Condition of Surfacing .			VS/U	
(c)	Riding Quality			√S/U	
d)	Road Camber			√S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.				Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts				S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3,	Road Furniture				
	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				
. (Compliance His	tory			
	Status of ATR's & any others				_

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	Apparatus i dela

NAME: