## FIELD INSPECTION REPORT

Date of Inspection : 0	3/12/20	District: Sitamarhi
Division: Cidamay	. A:	Length (km): 6.00 Km
Name of the Road: NH	77 Singmhiya	to bedusi Amghatta Path
Scheme/Programme:	MAINTENANCE	
Package No.: MRN/19 Status of the Project:	-20/sitamashi-02	Road Id No.:
Status of the Project:	Ongoing/Completed	/Under Maintenance
Work is a case of:		p gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	√S/U
b)	Condition of Surfacing	
(c)	Riding Quality	
d)	Road Camber	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	-8/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	
4.	Compliance History	
a)	Status of ATR's & any others	НО

Overall Rating

Satisfactory (S)	101 .
Satisfactory but requires Improvement (SRI)	1(3)
Unsatisfactory (U)	

(Signature)

NAME: Rohit kumax

DESIGNATION: J.E. RWD Sitamaski