FIELD INSPECTION REPORT

Data	EXECUTION REPORT	
Division	Inspection: 02, 12, 2020 District: Parna	
	Stho Pool Color Length (km): 0.600	17.19
	of the Road: Sazvoday City Adampus to Lake Programme: MAINTENANCE	ham Bigha
	e No.: MR-N 19-20-Danabus 08 Road Id No.:	
Status o	of the Project: Orgoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance		
SI. No.	Parameters to be checked	
11.7	Payement	Remarks
a)	Road Junction condition	
	温度	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2,	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	C/CDIAI
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
Y	Road Furniture	S/SRI/U
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
SHELLET, HE CO.	Compliance History	
a) S	Status of ATR's & any others	在1000年的
		£.

Overall Rating

Work not Started Satisfactory (S) Satisfactory but requires Improvement (SRI) Unsatisfactory (U)

chatulthy' Mandal

DESIGNATION: J.E.