FIELD INSPECTION REPORT

	THE RESERVE TO THE RE	Division Banka-2 Length (km): 4:15 K	. 1	
	the Road: Ka			
Scheme/Programme: MAINTENANCE Package No.: RM/84 BANT20 608 Road Id No.: 20 703602040				
Status of the Project: Ongoing/Completed/Under Maintenance				
Work is a	a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.		Parameters to be checked	Remarks	
1.	Pavement			
a)	Road Junction	unction condition S/U		
b)	Condition of Surfacing			ongoing on going
c)	Riding Quality			ongoing
d)	Road Camber			
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			NA
f)	Contraction Joints provided or not (CC Pavement)			NA .
g)	Compaction of flank/slope & raincuts if any			In progress
2.	Cross Draina			
a)	Condition of head walls in Hume pipe culverts including its painting			ongoing
b)	Condition of A	S/SRI/U	on going	
c)	Condition of railings/slab/approach for Bridges		S/SRI/U	on going
3.	Road Furniture			
a) :	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained Yes/No			ongoing
4.	Compliance History			
a) 1	Status of ATR's & any others			No.
Overall R				

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Status of work: - WBM poto and patch work is in Pougness.

(Signature) 2020

NAME: Knishna Kumar Simha

DESIGNATION: Executive Engineer

RWD Bank9-2.