

FIELD INSPECTION REPORT

Date of Inspection :	31/12/2020	District:	Munger
Division :	Kharagpur - Tamluk	Length (km):	2.290
Name of the Road:	Makwa - Bangarma		
Scheme/Programme:	MAINTENANCE		
Package No.:	N.O.	Road Id No.:	S.N.L
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	WORK NOT STARTED
b)	Condition of Surfacing	do
c)	Riding Quality	do
d)	Road Camber	do
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	do
g)	Compaction of flank/slope & raincuts if any	do
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	do
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	do
c)	Condition of railings/slab/approach for Bridges	do
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	do
4.	Compliance History	
a)	Status of ATR's & any others	N.

Overall Rating :

Satisfactory (S) <i>work not started till</i>
Satisfactory but requires Improvement (SRI)
Unsatisfactory (U)

Shailendra Kumar

(Signature)

NAME:

J.E