## FIELD INSPECTION REPORT

Date of Inspection: 02.12.2020 District: Kushangan			
Division: Kishangary 2 Length (km): 1,80 Km.			" Tak
Division: Kishangary - Length (km): 1.80 Km.  Name of the Road: Vagara (Bengal border to Belwa Pottiya Sado			
Scheme/Programme: I MAINTENANCE			Unde
Package No.: Road Id No.: 21205908034			New
Status of the Project: Orgoing/Completed/Under Maintenance  Work is a case of: New Connectivity/Up gradation/ Maintenance			Maint Poli
Work is a case of: New Connectivity/Op graduates Francisco			1 rou
Sl. No.		A STATE OF THE STA	
1.	Pavement	8/U	
a)	Road Junction condition		
b)	Condition of Surfacing	<b>8/U</b>	
c)	Riding Quality	\$/U	
	Road Camber 2	\$/U	
d) e)	Whether free from defects such as visible cracks, exposed	A . Yes/No	
	aggregates in case of CC Pavement.  Contraction Joints provided or not (CC Pavement)	Yes/No	
f)		Yes/No .	
g)	Compaction of flank/slope & raincuts if any		
2	Cross Drainage	a septat	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	HN.A.
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	4
c)	Condition of railings/słab/approach for Bridges	S/SRI/U	)
-3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	Societé.
4.	Compliance History		
a)	Status of ATR's & any others		
Overall I	Satisfactory (S)	"5"	
	Satisfactory but requires Improvement (SRI)	STORE .	
	TI-cottofootowy (ID)		

(Signature)

NAME:

-----

Scanned with CamScanner