FIELD INSPECTION REPORT

		FIELD INSPEC	CTION REPORT	<u> </u>
Date of Inspection: 03/12/2020 District: ARAR				
Division: FORBESGAND			Length (km):	
Name of the Road: Murgay to			Amona.	
Scheme/Programme: MAINTENANCE V			Road Id No.: 21206002	062
Fackage 100.				
Status of the Project:		New Connectivity/Un graduote Mante		
Work is a case of:		Parameters to	to checked	Remarks
Sl. No.	A COMMITTER OF	Parameters to		1917 2016
1.	Pavement			√S7U
a)	Road Junction condition			√S/ÎU
b)	Condition of Surfacing			VS/U
c)	Riding Quality			√8/U
d)	Road Camber Whether free from defects such as visible cracks, exposed **CC Payement** **A -			√Yes/No
e)	Vac/No			
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
	A invite if any			
2	The state of the s			
a)	Chood walls in Hume pipe culvens including			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in Recognition			s/srl/U
c)	Condition of railings/slab/approach for Bridges			
3.	To The Marie Control of the Control			111/2/2
a)	Whether sign boards/informatory/cautical and maintained			1
4.	Compliance History			
a)	Status of ATR'	s & any others		· · · · · · · · · · · · · · · · · · ·
,				=- 11 = 11

Overall Rating

	="S"-
Satisfactory (S)	
Satisfactory (S) Satisfactory but requires Improvement (SRI)	· · · · ·
Unsatisfactory (U)	

NAME:

Charding Slextar Sing L.
Arrif. Expenser
RND/FBG

Scanned by CamScanner