## FIELD INSPECTION REPORT

Date of It	spection: 02	112/2020	District: Naturada		
			Length (km): 1.00 km		
Name of			from NH31 to Pachasa vallage Th	- 2018	
	rogramme:	MAINTENANCE	New machine numerical		
Package	No.:		Road Id No.:		
Status of	the Project:	Ongaing/Complete	d/Under Maintenance		
Work is	a case of:		Up gradation/ Maintenance	Remarks	
SL No.	Parameters to be checked			Vehialies	
1.	Pavement				
a)	Road Junction condition			S/U	
b)	Condition of Surfacing			s/U	
c)	Riding Quality			S/U	
<u>d)</u>	Road Camber			S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
ŋ	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2	Cross Draina	ge .			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
14.	Compliance History				
a)	Status of ATR	C's & any others		Nil	

Overall Rating

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

02/12/2020

(Signature)

NAME: Binod Kumar shigh

DESIGNATION: Junior angineer

Scanned with CamScanner