FIELD INSPECTION REPORT

Date of li	nspection: 02	12/2020 District:	Nalanda		
Division :	121	Length (kn			
Name of	the Rond: Ber	al Saksohra Path Sc VIH19 41e	n Via Nana Ki Bho	r singh & tho	Sidheswa
Scheme/l	Programme:	MAINTENANCE		th ke Malcan	Tale
Package		Road Id No		, and a second	
	the Project:	Ongoing/Completed/Under Main		×	
Work is	n case of:	New Connectivity/Up gradation/	Maintenance		
Sl. No.		Parameters to be checked		Remarks	
1.	Pavement				
a)	Road Junction condition		SAL		
b)	Condition of Surfacing			S/U	
c)	Riding Quality			S/W	
d)	Road Camber			S/W	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)		Yes/No		
g)	Compaction of flank/slope & raincuts if any		Yes/Mo		
2	Cross Drainage			in Lan	
a)	Condition of head walls in Hume pipe culverts including its painting		SISRITU	The section of the se	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SPA/U		
c)	Condition of railings/slab/approach for Bridges		S/SRI/U		
3.	Road Furnit	ıre			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
建 山岭	Compliance	History		(中)	54 9.7
a)	Status of AT	C's & any others		-No-	

Overall Rating

Satisfactory (S)		S
Satisfactory but requires	Improvement (SRI)	
Unsatisfactory (U)		

(Signature)

NAME: Mukesh Eadur

DESIGNATION: J. &.

Scanned with CamScanner