FIELD INSPECTION REPORT

vision :	Bikarsh	2-12-2020 and	Length (km): 3.0 KM		
ime of th			Khuran Via Maulanggar Roa	d.	
	ogramme:	MAINTENANCE			
ackage N			Road Id No.:		
	he Project:		eted/Under Maintenance		
Vork is a	case of:	·	ty/Up gradation/ Maintenance		
SI. No.	No. Parameters to be checked			Remarks	
1.	Pavement				
a) .	Road Junction condition			S/U	S
b)	Condition of Surfacing			S/U	5
c)	Riding Quality			S/U	S
(ل	Road Camber			S/U	S
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	40
ŋ	Contraction Joints provided or not (CC Pavement)			Yes/No	14-6
g)	Compaction of flank/slope & raincuts if any			Yes/No	٦,
2	Cross Drainage				7
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U	7	
b)	Condition of Abutment & Wing		ing walls, Slab in RCC culverts	S/SRI/U	1
c)	Condition of railings/slah/approach for Bridges		S/SRI/U	\dashv)	
3.	Road Fur	niture			4
a) Whether sign be stones/Pavement		sign boards/infor vement road marki	oards/informatory/cautionary Board/km & 200m road markings are provided and maintained		y
W. T.	Compliance History				-
a) Status of ATR's & any other		ATR's & any other	rs.	NIL	-
Ove	rall Rating				
Satisfact			The state of the s	2	
		Satisfact	ory but requires Improvement (SRI) setory (U)		-

(Signature)

NAME: Arvind Kumer

DESIGNATION: J. C.