FIELD INSPECTION REPORT

Date of	Inspection: Office District: Shape approx		
Division	: Kahalgaan Length (Iran)	i I	
Name o	f the Road: al. Length (km): 7.77	Kun	
Scheme	Programme: Marayanpur Se Kuhandaspur	Hote hue	Tabua Ekchari
Packag	f the Road: Shir narayantur se Kuhandaspur Programme: MAINTENANCE No.: Road Id No. 2007 5750	respons on	m Dilawi Barak
Status (f the Project: Ongoing/Completed/Linder Maintenance	033	
Work is	Some Completed Olider Maintenance	birtena	nce
Sl. No.	Maintenance Maintenance	ntenances	٥.
1.	narameters to be checked	Remarks	
100000000000000000000000000000000000000	Payement	1000	
a)	Road Junction condition	S/tď	3
b)	Condition of Surfacing	S/6	\$
c)	Riding Quality	S/L	3
d)	Road Camber	S/L	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	yes
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	NA
g)	Compaction of flank/slope & raincuts if any	Yes/No	NA
2.,	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	NA
c)	Condition of railings/slab/approach for Bridges	S/SRIFU	NA
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	Yes
A	Compliance History	冷观 器	3
a)	Status of ATR's & any others	No	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Road Id No. 20703408033 and 20703408037 are Some.

3. Treens

(Signerture) 11 M

NAME: