FIELD INSPECTION REPORT

Date of Inspection:	2-12-2020	District: Suparl		
Division: Works I	Division Birbus	Length (km): 8.43		
Name of the Road: Repair of Road from NH57 to Baira Via Brokenpur				
Scheme/Programme:	MAINTENANCE			
Package No.:	1	Road Id No.: 21005008053		
Status of the Project:	Ongoing/Completed/Under Maintenance			
Work is a case of:	New Connectivity/Up gradation/ Maintenance			

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	√\$/U
b)	Condition of Surfacing	√ 8/U
c)	Riding Quality	\ 8/U
d)	Road Camber	√8/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	√S/SRI/U
c)	Condition of railings/slab/approach for Bridges	√S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	Not Request

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: ARSUN PRASAD

DESIGNATION: CG. RELD Works Division

Scanned by CamScanner