## FIELD INSPECTION REPORT

	ESSO INDIES	ALON ROLLAND	
f Inspection : 0 2	2-19-2020	District: Kishangy	
Division · Lata		Laugth (km): 1,850	
of the Road: K	epair of roa	of from LRP. Baluban to	Nimbugan
e/Programme:	MAINTENANCE		
ge No.:		Road Id No.: 21203700	755
	Ongoing/Completed	In andation/ Maintenance	
PERSONAL AND MINISTER OF THE PROPERTY OF THE P	New Connectivity/C	P B AND A THE TANK A STATE OF THE PARTY OF T	Remarks
	Parameters 19	到14 10 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	
Pavement	.,		S/U
a) Road Junction condition			S/U V
Condition of S	urfacing		
			LS/U
			V S/U
Road Camber	Sam defects such	as visible cracks, exposed	Yes/No V
Whether free from defects such as visite as aggregates in case of CC Pavement.			
Contraction Joints provided or not (CC Pavement)		Yes/No V	
		Yes/No .	
Compaction of	tiank/slope & failleur	Sin any	
Cross Drainag	e i initia		S/SRI/U
Condition of head walls in Hume pipe culverts including its painting			
Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
Condition of Accument		S/SRI/U	
TO A THE PARTY OF		BOOK WELL TO A SECOND	
Property of the Party of the Carlot and Delegated the Alline St. Carlot		triare de la companya	
Whether sign stones/Pavemen	boards/informatory/o t road markings are I	autionary Board/km & 200m provided and maintained	Yes/No L
Compliance Hi	story		1.62
Status of ATR's	& any others		
	of the Road: Ke/Programme: ge No.: of the Project: is a case of:  Pavement Road Junction Condition of Significant Road Camber Whether free aggregates in contraction Join Compaction of Condition of Air Condition	on: Kishengari-2 of the Road: Repair of roade/Programme: MAINTENANCE ge No.: of the Project: Ongoing/Completed is a case of: New Connectivity/U Parameters to Pavement Road Junction condition Condition of Surfacing Riding Quality Road Camber Whether free from defects such aggregates in case of CC Pavement. Contraction Joints provided or not (Compaction of flank/slope & raincus Cross Drainage Condition of head walls in Hume pip Condition of Abutment & Wing wall Condition of railings/słab/approach in Road Furniture	of the Road: Re pour of road from LRP Baluban to e/Programme: MAINTENANCE ge No.: Road Id No.: 212059080 of the Project: Ongoing/Completed/Under Maintenance New Connectivity/Up gradation/ Maintenance Parameters to be checked  Pavement Road Junction condition Condition of Surfacing Riding Quality Road Camber Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. Contraction Joints provided or not (CC Pavement) Compaction of flank/slope & raincuts if any Cross Drainage Condition of head walls in Hume pipe culverts including its painting Condition of Abutment & Wing walls, Slab in RCC culverts Condition of railings/slab/approach for Bridges Road Furniture Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained  Gompliance History  Gompliance History

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI

NAME: Ajit Kumar
JE/Thakurganj