

### FIELD INSPECTION REPORT


|                                                               |  |                          |
|---------------------------------------------------------------|--|--------------------------|
| Date of Inspection : 3.12.2020                                |  | District: Araria         |
| Division : Araria                                             |  | Length (km): 7.5 km      |
| Name of the Road: PWD Dhakea Li Baigama                       |  |                          |
| Scheme/Programme: MAINTENANCE                                 |  |                          |
| Package No.:                                                  |  | Road Id No.: 21206008120 |
| Status of the Project: Ongoing/Completed/Under Maintenance    |  |                          |
| Work is a case of: New Connectivity/Up gradation/ Maintenance |  |                          |

| Sl. No. | Parameters to be checked                                                                                             | Remarks    |
|---------|----------------------------------------------------------------------------------------------------------------------|------------|
| 1.      | <b>Pavement</b>                                                                                                      |            |
| a)      | Road Junction condition                                                                                              | ✓ S/U      |
| b)      | Condition of Surfacing                                                                                               | ✓ S/U      |
| c)      | Riding Quality                                                                                                       | ✓ S/U      |
| d)      | Road Camber                                                                                                          | ✓ S/U      |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | N/A Yes/No |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                     | N/A Yes/No |
| g)      | Compaction of flank/slope & raincuts if any                                                                          | ✓ Yes/No   |
| 2.      | <b>Cross Drainage</b>                                                                                                |            |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                                 | ✓ S/SRI/U  |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | S/SRI/U    |
| c)      | Condition of railings/slab/approach for Bridges                                                                      | S/SRI/U    |
| 3.      | <b>Road Furniture</b>                                                                                                |            |
| a)      | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | ✓ Yes/No   |
| 4.      | <b>Compliance History</b>                                                                                            |            |
| a)      | Status of ATR's & any others                                                                                         | N/A        |

Overall Rating :

|                                             |   |
|---------------------------------------------|---|
| Satisfactory (S)                            | S |
| Satisfactory but requires Improvement (SRI) |   |
| Unsatisfactory (U)                          |   |

  
 (Signature)

NAME: P. K. Poddar  
 DE PWD Araria