FIELD INSPECTION REPORT

DARBHANGA District: Date of Inspection: 02/12/2020 Length (km): 5KM Division: BENIPUR Name of the Road: Repair of Road form Tardih block to Madaria via Bainka MAINTENANCE Scheme/Programme: Road Id No .: Package No.: Ongoing/Completed/Under Mainterfance Status of the Project: New Connectivity/Up gradation/ Maintenance Work is a case of: Remarks Parameters to be checked SI. No. Pavement 1. S/U Road Junction condition a) S/U Condition of Surfacing b) S/U Riding Quality c) \\$/U d) Road Camber Yes/No Whether free from defects such as visible cracks, exposed e) aggregates in case of CC Pavement. Yes/No Contraction Joints provided or not (CC Pavement) n Yes/No Compaction of flank/slope & raincuts if any g) 2. **Cross Drainage** Condition of head walls in Hume pipe culverts including its painting a) S/SRI/U Condition of Abutment & Wing walls, Slab in RCC culverts b) S/SRI/U Condition of railings/slab/approach for Bridges c) S/SRI/U 3. Road Furniture Whether sign boards/informatory/cautionary Board/km & 200m a) Yes/No stones/Pavement road markings are provided and maintained 4. Compliance History a) Status of ATR's & any others

Overall Rating

Satisfactory (S)	(5)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

TE (मारडीह)

Sharli 2/12/2010 AE (Tardih) 5 To from

(Signature)

NAME: PRADEED KUNAR

DESIGNATION: -J.E