

FIELD INSPECTION REPORT

Date of Inspection : 03-12-2020		District : GAYA	
Division : Neemchak Bathani ; Sub Division - Manpur.		Length (Km. :	
Scheme/Programme: M/R-3054		MAINTENANCE <i>Gaya Sarbahda to Budhi Road (Class II)</i>	
Package No. : N/A		Road Id No. : N/A .	
Status of the Project : <i>Ongoing</i>		Ongoing/Completed/Under Maintenance	
Work is a case of : <i>Maintenance</i>		New Connectivity/Up gradation/Maintenance	
Sl. No.	Parameters to be checked		Remarks
1 Pavement			
a)	Road Junction condition	S	S/U
b)	Condition of Surfacing	S	S/U
c)	Riding Quality	S	S/U
d)	Road Camber	S	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N/A	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	N/A	Yes/No
g)	Compaction of flank/slope & raincuts if any	<i>Work in progress</i>	Yes/No
2 Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting	N/A	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N/A	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	N/A	S/SRI/U
3 Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	<i>Yes.</i>	Yes/No
4 Compliance History			
a)	Status of ATR's & any others.	<i>No any ATR</i>	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

AB
03/12/2020.
A.E. R.W.D.
Manpur.