FIELD INSPECTION REPOR

| | | - INSTEC | CTION REPORT | | |
|---------------|--|--|------------------------------------|--------------|--|
| ate of Ir | spection: 03 | 118.2020 | District: 5 | | |
| rision: Busex | | | District: Buxas Length (km): 3.750 | | |
| ame of | the Road: chas | usa-Geda Ramgar | the Path to Niknish Sogra Uni | In Molantal | |
| | | MAINTENANCE | TOTAL TOTAL SOUTH ON | VALLE (2001) | |
| ackage | | | Road Id No.: | | |
| atus of | the Project: a case of: | Ongoing/Completed | d/Under Maintenance | | |
| | a case of: | The second second second second second | Up gradation/ Maintenance | | |
| Sl. No. | | Parameters to | be checked | Remarks | |
| 1. | Pavement | | | | |
| a) | Road Junction condition | | | S/U | |
| b) | Condition of Surfacing | | | S/U | |
| c) | Riding Quality | | | S/U | |
| d) | Road Camber | | | S /U | |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | | | | |
| 1) | Contraction Joints provided or not (CC Pavement) Yes/No | | | Yes/No | |
| g) | Compaction of flank/slope & raincuts if any Yes/No | | | | |
| 2. | Cross Drainage | | | | |
| a) | Condition of head walls in Hume pipe culverts including its painting S/SRI/I | | | S/SRI/U | |
| b) | Condition of Abutment & Wing walls, Slab in RCC culverts S/SR | | | S/SRI/U | |
| c) | Condition of railings/slab/approach for Bridges S/S | | | S/SRI/U | |
| 3. | Road Furniture | | | | |
| a) | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | | | | |
| 94 | Compliance | History | Stockers Control of | 1 500 | |
| | UNA PRESIDENTIAL PROPERTY AND ADDRESS OF THE PARTY AND ADDRESS OF THE P | R's & any others | | No. | |

| Satisfactory (S) | `S' |
|---|-----|
| Satisfactory but requires Improvement (SRI) | |
| Unsatisfactory (U) | |

NAME: Maya Ward Rosed

DESIGNATION: J.E.