FIELD INSPECTION REPORT

	Inspection: 02.12.2020 District: Partua	
Division	I Danabus Length (km): 10-0	
Name of	f the Road: Rik puram chork to Ashopur Mathyaput	path via
Scheme	Programme: MAINTENANCE	
	No.: MR-N/19-20-Daraputo3 Road Id No.:	
	f the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1	Payement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2. (Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No-
4,14	Compliance History	
a)	Status of ATR's & any others	

Overall Rating

Satisfactory (S)	<
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: chatulthuy Mandel

DESIGNATION: J.E.