

FIELD INSPECTION REPORT

Date of Inspection:	02.12.2020	District:	DARBHANGA
Division:	DARBHANGA - 2	Length(Km):	03.00 KM.
Name of Road:	SAHANPUR SHYAM CHOWK TO LAKHANPUR.		
Scheme/Programme:	Maintenance MR-3054		
Package No.		Road Id No.	
Status of the Project:	Ongoing/Completed/ Under Maintenance		
Work is a case of:	New Connectivity/Up-gradation/ Maintenance		
S No.	Parameters to be Checked	Remarks	
1	Pavement BT		
a)	Road Junction condition	✓ S/Ux	
b)	Condition of Surfacing	✓ S/Ux	
c)	Riding Quality	✓ S/Ux	
d)	Road Camber	✓ S/Ux	
e)	Whether free from defects such as visible cracks, exposed * aggregates in case of CC Pavement (CC PAVEMENT)	✓ Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No	
g)	Compaction of flank /slope & raincuts if any	✓ Yes/Nox	
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U	
b)	Condition of Abutment & Wing walls , Slabs in RCC culverts	S/SRI/U NA	
c)	Condition of railing /slabs/ approach for Bridges	S/SRI/U NA	
3	Road Furniture		
a)	Whethersign boards/ informatory/ cautionary Board / Km & 200m stones/ Pavement road markings are provided and maintained	✓ Yes/No	
3	Compliance History		
a)	Status of ATR's & any others	NO	
Overall Rating:			
Satisfactory (S)		—	
Satisfactory but requires Improvement (SRI)		SRI	
Unsatisfactory (U)		—	

Name:

(Signature)

Designation:

* Heavily sub-mergence flow of water during flood period, revealing shown on wearing surface of cc pavement portion.
Hence on the above mentioned facts it is directed that the relaying of wearing surface on the cc pavement portion on top priority.
03/12/20
AC/ Singh