## FIELD INSPECTION REPORT

Date of Inspection: 2.12.20 District: 1/4/014 C				
Division: Bhabua Length (km): 349				
Name of the Road: THABLA HUNAA BO TO JAGE BADWALD				
Scheme/Programme: MAINTENANCE 31161 (hAz h Mai Mailea				
Package No.: MAN /20/9020 / Page Road Id No.: 10/20/00/20/				
Status of the Project: Ongoing/Completed/Linder Maintenance				
Work is a case of: New Connectivity/Up gradation/ Maintenance				
SI. No.	Parameters to be	cheeked	Remarks	
1.	Pavement			
a)	Road Junction condition		· S/U	
b)	Condition of Surfacing		S/U	
c)	Riding Quality		S/U	
<u>d)</u>	Road Camber		S/U	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No	
f)	Contraction Joints provided or not (CC Pavement)		Yes/No	
g)	Compaction of flank/slope & raincuts if any		Yes/No	
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U	
<u>b)</u>	Condition of Abutment & Wing walls	, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges		S/SRI/U	
3.	Road Furniture			
a)	Whether sign boards/informatory/costones/Pavement road markings are pro-	nutionary Board/km & 200m rovided and maintained	Yes/No	

Overall Rating

4.1

Satisfactory (S)	_
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: Shashi Bhaashan Kumay

Compliance History

Status of ATR's & any others

DESIGNATION: A. E.

Scanned with CamScanner