## FIELD INSPECTION REPORT

Block - Sultangry.

Date of Inspection: 3.12.20 District: Bragalow. (Sultanganj ) Blychm | Length (Km): Division: Name of the Road: MH-80 to Purani motichare Via Schabael. Scheme/Programme: MAINTENANCE Package No.: | Road Id No.: 27321031915 Group No. 10 Ongoing /completed/Under Maintenance Status of the Project: Work is a case of: New Connectivity/Up gradation/ Maintenance Remarks SL. No. Parameters to be checked 1 **Pavement** S/U Road Junction condition a) S/U **Condition of Surfacing** b) S/U **Riding Quality** c) S/U **Road Camber** d) Whether free from defects such as visible cracks, exposed Yes/No e) aggregates in case of CC Pavement. Yes/No Contraction Joints provided or not (CC Pavement) f) Yes/No Cpmpaction of flank/slope & raincuts if any g) **Cross Drainage** 2 Condition of head walls in Hume pipe culverts including its painting S/SRI/U a) NA S/SRI/U Condition of Abutment & Wing Walls, Slab in RCC culverts b) S/SRI/U Condition of railings/slab/approach for Bridges C) **Road Furniture** Whether sign boards/informatory/cautionary Board/km & 200m Yes/No stones/Pavement road markings are provided and maintained a) **Compliance History** Status of ATR's & any others work has Not been Stuteet Yet. Overall Rating:

Satisfactory(S) Satisfactory but requires Improvement (SRI) Unsatisfactory(U)

NAME: 11. N. manto.

Scanned with CamScanne

NA