

FIELD INSPECTION REPORT

Date of Inspection : 2/12/2020	District: Nalanda
Division : Rajgir	Length (km): 3.5 km.
Name of the Road: Chabilapur Dharehara Path se Dillu bigha Hote hue vijay nagar Path	
Scheme/Programme: MAINTENANCE	(3054 MR)
Package No.: Batch RM/NA/RAJ/20/0004	Road Id No.: 1291033581
Status of the Project: Ongoing/Completed/Under Maintenance	Ongoing
Work is a case of:	New Connectivity Up gradation Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓
b)	Condition of Surfacing	✓
c)	Riding Quality	✓
d)	Road Camber	✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No (NA)
f)	Contraction Joints provided or not (CC Pavement)	Yes/No (NA)
g)	Compaction of flank slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U (NA)
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U (NA)
c)	Condition of railings slab approach for Bridges	S/SRI/U (NA)
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No (Work in progress)
4.	Compliance History	
a)	Status of ATR's & any others	NO


Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

S


2.12.20
(Signature)

NAME: - Kishor Kumar
Assistant Engineer
Rajgir.