FIELD INSPECTION REPORT

Vame	RND(W)	Airision Banka-2	District: Banka Length (km): 1-500		
vame o	the Moad: Ch	Mraixa Mahua	More to Kolhasar		
		MAINTENANCE			
Status	f the Project:	BAN 19 10001 1	Road Id No.: 20703502	229	
	a case of:	Queen Connection at	Inder Maintenance		
Sl. No.		Trew Connectivity/Up	gradation/ Maintenance		
1.	Parameters to be checked		Remarks		
1001/6/0068	Pavement				
a)	Road Junction condition			VS/U	
b)	Condition of Surfacing			S/U	
c)	Riding Quality			√S/U	
d)	Road Camber			S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
4.	Compliance Hi	story			
a)	Status of ATR's & any others				

Overall Rating

Satisfactory (S)	5
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: Bikrama Prasad

DESIGNATION: Assistant Engèncer

Kathright.