FIELD INSPECTION REPORT

		11.01.17	<u> LITON REPORT</u>		
te of In	spection: 03	11212020	I Division and a second		
Date of Inspection: 03/12/2020 Division: Biharshard			District: Nalander		
ame of t	ne Kond: (2)	Delaka Valda	Length (km): 1.80 K· U. igos fathese Muzzipachak		
		MAINTENANCE	afor tothese in wish package		
ackage l			Road Id No.:		
latus of	the Project:	Onguing/Complete	d/Under Maintenance		
	case of:	New Connectivity/	Up gradation/ Maintenance		
SI. No.	Parameters to be checked		Remarks		
1.	Pavement				
a)	Road Junction condition S/U				
b)	Condition of Surfacing			S/U	
c)	Riding Quality			S/U	
d)	Road Camber			S/U	
c)	Whether free from defects such as visible cracks, exposed Yes/No aggregates in case of CC Pavement.				
f)	Contraction Joints provided or not (CC Pavement) Yes/N				
g)	Compaction of flank/slope & raincuts if any Yes/No				
27	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting S/SRI/I				
b)	Condition of Abutment & Wing walls, Slab in RCC culverts				
c)	Condition of railings/slab/approach for Bridges S/SR			S/SRI/U	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				
産は特	Compliance History				
a)	Status of ATR's & any others			- WO-	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

NAME: Mukesh Yadeus

DESIGNATION: J.E.

(Signature)

Scanned with CamScanner