FIELD INSPECTION

		THE INSPEC	CTION DEPOND		
Tate of I	aspection:	3/12/2020	CTION REPORT		
Division :		havil	District: Nalanda		
iame of	the Road: N	H83			
icheme/l	rogramma	MAINTENANCE	n To Deshing		
MCKAEC	10.	MAINTENANCE			
intus of	the Project:	Oppoint/Co.	Road Id No.:		
Work is a second with the second seco					
SI. No.	New Connectivity/Up gradation/ Maintenance  Parameters to be checked				
1.	Pavement	l'arameters (o	be checked	Remarks	
n)	Road Junction condition			S/U	
b)	Condition of Surfacing			S/U	
c)	Riding Quality			S/U	
d)	Road Camber			S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2.1	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
學的學	Compliance History				
a)	Status of ATR	s & any others		100	

Overall Rating

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Mukelh Yadau

DESIGNATION: LE