FIELD INSPECTION REPORT

	heme Programme MAINTI NAME	
	chage No. Road Id No.:	
	this of the Project Outpoint Completed Cides Maintenance New Completed Cides Maintenance New Complete Cides Completed Cides Maintenance	
		Remarks
	Taranters to de Cherken	
	Pavement	-
28	Read Junction condition	y .
ŀ	Condition of Surfacing	UK I
6	Riding Quality	Jr."
di	Road Camper	×
e)	Whether free from defects such as visible cracks, expused aggregates in case of CC Pavement.	Yes/No
n	Contraction Joints provided or not (CC Pavement)	Jes No
g)	Compaction of flank/slope & raincuts if any	yes No
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	& SRIU
:)	Condition of railings/slab/approach for Bridges	& SRLU
	Road Furniture	
	Whether sign boards/informatory cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	XesNo
1	Comp'tuace History	
5	tatus of ATR's & any others	NO
H Pa	tie a	
II Ra	Satisfactory (S)	5
	Satisfactory but requires Improvement (SRI)	-
	Sensing of tequites improvement (See	

1E: 2:100 - 02112 NO

6,071