FIELD INSPECTION REPORT

te of Ir	Spection	
sion :	sion: Rilanda District: Naturda	
ne of	he Ronde 2 Length (km): 0.810	
eme/i	Ingramme: MAINTENANCE	Meye.
ckage	Vo.:	
atus of	the Project: Ongoing/Completed/Under Maintenance	
	New Connectivity/Up gradation/ Maintenance	
l. No.	Parameters to be checked	Remarks
1.	Pavement	
n)	Road Junction condition	S/U C
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U /
c)	Whether free from defects such as visible cracks, expose aggregates in case of CC Pavement.	S/U d Yes/No
ŋ	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	ng S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
. 3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200 stones/Pavement road markings are provided and maintained	Om Yes/No
包持	Compliance History	
a)	Status of ATR's & any others	

Overall Rating

Satisfactory (S)
Satisfactory but requires Improvement (SRI)
Unsatisfactory (U)

(Signature)

NAME:

Mucesh Eaday

DESIGNATION: J. S