


FIELD INSPECTION REPORT

Date of Ins:	2-12-2020	District:	NALANDA
Division :	HARNAUT	Length (km):	0.300
Name of the	CHERO NAGARHUSA PALSY ROAD TO HRIDAN BIHA		
Scheme Program	MAINTENANCE		
Package No.	MR-N/19-Harna/01	Road Id No.:	
Status of the	Ongoing/Completed/Under Maintenance		
Work is a	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a.	General condition		✓S/U
b.	Condition of Surfacing		✓S/U
c.	Base		✓S/U
d.	Subgrade		✓S/U
e.	Whether free from defects such as visible cracks, exposed aggregate, etc. (CC Pavement)		Yes/No
f.	Curbs provided or not (CC Pavement)		Yes/No
g.	Condition of flaps, slope & raincuts if any		✓Yes/No
2.	Structure		
a.	Condition of culverts including its painting		S/SRI/U
b.	Condition of abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c.	Condition of railing/slab/approach for Bridges		S/SRI/U
3.	Signage		
a.	Whether board/informatory/cautionary Board/km & 200m markings are provided and maintained		✓Yes/No
4.	Other		
a.	Other & others		

Overall

Satisfactory (S)		'S'
Satisfactory but requires Improvement (SRI)		
Unsatisfactory (U)		


(Signature)

NAME: MUKESH KUMAR SINGH