## FIELD INSPECTION REPORT

Date of Inspection :	03.12.2020	District: Sitomashi
Division :	Belsand.	Length (km):
Name of the Road:	Kharnua 3	o sugaidin.
Scheme/Programme:	MAINTENANCE	
Package No.:		Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	

Sl.	No.	Parameters to be checked	Remarks
•	1.	Pavement	
ı	a)	Road Junction condition	S/U/
I	b)	Condition of Surfacing	S/U
	c)	Riding Quality	S/U
•	d)	Road Camber	· S/U
	e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
	f)	Contraction Joints provided or not (CC Pavement)	Yes/No
•	g)	Compaction of flank/slope & raincuts if any	Yes/No
	2.	Cross Drainage	
	a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
	b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
•	c)	Condition of railings/slab/approach for Bridges	S/SRI/U
	3.	Road Furniture	
	a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
•	4.	Compliance History	
	a)	Status of ATR's & any others	NO.

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	""

(Signature)

NAME: Visnod Kumar sah.

DESIGNATION: A.E.