FIELD INSPECTION REPORT District: East. champaran.
Last. champaran.
Last. champaran.
Length (Km): 6.90 cm.
Raplway Gymorti Meksi to Palte Belwa via Paism frum. Division: 03/12/2020 Division: Name of the Road: MAINTENANCE (0LD) Scheme/Programme: 3/20840 Package No.: Road ID No.: Ongoing/Completed/Under Maintenance Status of the Project: Work is a case of: New Connectivity/Up Gradation/ Maintenance SI. No. Parameters to be checked Remarks 1. **Pavement** 101 a) Road Junction condition 101 b) Condition of Surfacing 151 c) Riding Quality 151 d) **Road Camber** Whether free from defects such as visible cracks, exposed aggregates in e) case of CC Pavement. f) Contraction Joints provided or not (CC Pavement) g) Compaction of flank/slope & raincuts if any Cross Drainage 2, NO a) Condition of head walls in Hume pipe culverts including its painting b) Condition of Abutment & Wing walls, Slab in RCC Culverts c) Condition of railings/slab/approach for Bridges 3. Road Furniture Whether sign board/informatory/cautionary Board/Km & 200m NO a) Stones/Pavement road markings are provided and maintained **Compliance History** 4, a) Status of ATR's & any others Satisfactory (S) **Overall Rating** Satisfactory but requires improvement (SRI) Unsatisfactory (U) Remarks-Same Portion Lamage du to water lugging (Signature) NAME: **DESIGNATION:** Zala 2020 03/X11/2020