FIELD INSPECTION REPORT

| Date of Inspection: District: East chanfaran, Motin | | | | | |
|---|--|---------------------|-------------------------|------------|--|
| Division: Works Division Pakridaya | | | Length (km): 1.900K·M | | |
| | the Road: Po | eth Khauliya siv | van to Bakhori Main roc | 10 | |
| | Programme: | MAINTENANCE (| New Maintenance Policy- | 2018 | |
| Package No.: | | | Rond Id No.: | | |
| | | | /Under Maintenance | | |
| Work is a case of: New Connectivity/Up gradation/ Maintenance | | | | | |
| Sl. No. | | Parameters to | be checked | Remarks | |
| 1. | Pavement | | | | |
| a) | Road Junction condition | | | √S/U | |
| b) | Condition of Surfacing | | | ~S/U | |
| c) | Riding Quality | | | √S/U | |
| d) | Road Camber | | | √S/U | |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | | | Yes/No | |
| f) | Contraction Joints provided or not (CC Pavement) | | | Yes/No - N | |
| g) | Compaction of flank/slope & raincuts if any | | | √Yes/No | |
| | Gross Drainage | | | | |
| a) | Condition of head walls in Hume pipe culverts including its painting ~S/ | | | ~S/SRI/U | |
| b) | Condition of Abutment & Wing walls, Slab in RCC culverts | | | ✓S/SRI/U | |
| c) | Condition of railings/slab/approach for Bridges | | | √8/SRI/U | |
| | Road Furnit | ure Ore | | - A | |
| a) | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | | | | |
| | Completion California - N/A - | | | | |
| a) | Status of ATI | R's & any others | | | |
| | | Tay military in the | | | |

Overall Rating

| | A STATE OF THE PARTY OF THE PAR |
|---|--|
| Satisfactory (S) | M5" |
| Satisfactory but requires Improvement (SRI) | |
| Unsatisfactory (U) | |

312/20 OB/12/24 312/20 AR

(Signature)