

FIELD INSPECTION REPORT

Date of Inspection:	02.12.2020	District:	DARBHANGA
Division:	DARBHANGA-2	Length(Km):	5.5 KM
Name of Road:	SEMRI - SINGHWARA PATH TAK MARAMMATI KARYA		
Scheme/Programme:	Maintenance - MR-3054		
Package No.		Road Id No.	
Status of the Project:	Ongoing/Completed/ Under Maintenance ✓		
Work is a case of:	New Connectivity/Up gradation/ Maintenance ✓		

S No.	Parameters to be Checked	Remarks
1	Pavement (BT)	
a)	Road Junction condition	✓S/UA
b)	Condition of Surfacing	✓S/U✓
c)	Riding Quality	✓S/U✓
d)	Road Camber	✓S/U✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement (CC PAVEMENT)	Yes/No✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No✓
g)	Compaction of flank /slope & raincuts if any	Yes/No✓
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U NA
b)	Condition of Abutment & Wing walls, Slabs in RCC culverts	S/SRI/U NA
c)	Condition of railing /slabs/ approach for Bridges	S/SRI/U NA
3	Road Furniture	
a)	Whethersign boards/ informatory/ cautionary Board / Km & 200m stones/ Pavement road markings are provided and maintained	Yes/No✓
3	Compliance History	
a)	Status of ATR's & any others	NO
Overall Rating:		
Satisfactory (S)		—
Satisfactory but requires Improvement (SRI)		—
Unsatisfactory (U)		U


Heavily Submergence & flow of water during flood period, partial constructed length was partially damaged at about full length.

Name:

Designation:

As per guidelines given by Sec - RWD (G.O.B.) for early movement of vehicle temporary restoration work has been done.

(Signature)


 03/12/20
 A.C. Singh