

FIELD INSPECTION REPORT

Date of Inspection : 2/12/2020 District: Nalanda
 Division : Rajgir Length (km): 1.005 km.
 Name of the Road: chabilapur mor se chadura gaon tk
 Scheme/Programme: MAINTENANCE
 Package No.: Road Id No.: 10200908037
 Status of the Project: Ongoing Completed Under Maintenance Maintenance
 Work is a case of: New Connectivity Up gradation Maintenance Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S U
b)	Condition of Surfacing	✓ S U
c)	Riding Quality	✓ S U
d)	Road Camber	✓ S U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No (NA)
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S SRI ✓ (NA)
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S SRI ✓ (NA)
c)	Condition of railings/slab approach for Bridges	S SRI ✓ (NA)
3.	Road Furniture	
a)	Whether sign boards/informatory cautionary Board km & 200m stones/Pavement road markings are provided and maintained	Yes/No (SRI)
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

SRI

Rampresh kumar

NAME:

SE
Rajgir

2/12/20
JE
(Signature)