

FIELD INSPECTION REPORT

Date of Inspection : 03/12/2020		District: Madhepura	
Division : Uda Kisanganj		Length (km): 3.80 km	
Name of the Road: NH-106 Fulaut to dhaneshpur			
Scheme/Programme: MAINTENANCE		Road Id No.: 21004808045	
Package No.:		Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement	✓ S/U	
a)	Road Junction condition	✓ S/U	
b)	Condition of Surfacing	✓ S/U	
c)	Riding Quality	✓ S/U	
d)	Road Camber	Yes/No	N.A.
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	N.A.
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any (Due to flood)	Yes/No	
2.	Cross Drainage	S/SRI/U	} N.A.
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	Road Furniture	Yes/No	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No	
4.	Compliance History	NO	
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Remarks : - Some part damage due to flood - 2020

AK
03/12/2020
AE.

(Signature)
03/12/2020

NAME:

SATOSH KUMAR