FIELD INSPECTION REPORT

Date of Inspection:		02/12/2020	District	: Darbhanga
Division:		Biraul	Length(Km)	
Name of Road:		Koshi Bandh To k	athal	
Scheme/Progrmme:		Maintenance		
Package No.		NIL	Road Id No.	
Status of the Project:		Ongoing/Completed/ Under Maintenance		
Work is a case of:		New Connectivity/Up gradation/ Maintenance		
S No. Pa		rameters to be Checcked		Remarks
1	Pavement			
a)	Road Junction condition			S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	Road Camber			۵/۷ی
e)	Whether free from defects such as visible cracks, exposed			
	aggregates in case of CC Pavement			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank /slope & raincuts if any			Yes/No
2	Cross Drainage			
a)		valls in Hume pipe culverts in	cluding its	s/srl/u
	painting			0/9.70
b)	Condition of Abutment & Wing walls , Slabs in RCC culverts		S/SRI/U	
c)	Condition of railing /slabs/ approach for Bridges			S/SRL/U
3	Road Furniture			
a)	Whethersign boards/ informatory/ cautionary Board / Km & 200m stones/ Pavement road markings are provided and maintained			Yes/No
3	Complianace History			
	Status of ATR's & any			No
-				
Overall Rating:				
	s	atisfactory (S)		(COT)
		atisfactory but requires Imp	rovement (SRI)	(SRI)
Unsatisfactory (U)				
Jeets in road patrion are due to submargence and out 2.12 rown of water discharge due to heavy flood. (Signature)				
our of water discrarge due to heavy flood. (Signature)				

A Defects in road position are due to submergence and show of water discharge due to heavy shood.

Name: Anil kumaz

Designation: Executive Engineer

Scanned with CamScanner