FIELD INSPECTION REPORT

Date of Inspection :	12-12-2020	District: Madhabasi	
The A. A. A. A.	nepass	Length (km): 4-9000 KM.	
Name of the Road:	Beehwood to Ke	a 5 mackly Check	
Scheme/Programme: MAINTENANCE			
Package No.: Bethu	eró more te Krome	Road Id No.:	
Status of the Project:	Advantage in the second	fed/Under Maintenance	
Work is a case of:	prepare take dilatera sekalegas errestil (re. r. p. br. r. f. f. att a generaliseter kritiketer kritiketer kri	y/Up gradation/ Maintenance	

SI. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition		
b)	Condition of Surfacing		
c)	Riding Quality		
d)	Road Camber		
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		
n	Contraction Joints provided or not (CC Pavement)		
g)	Compaction of flank/slope & raincuts if any		
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SPA/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	_8/SRI/U	
c)	Condition of railings/slab/approach for Bridges	√8/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		
14.00 T	Compliance History	NO	
a)	Status of ATR's & any others		

Overall Rating

Satisfactory (S)	111
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Qianature) (Signature)

NYME: AD-A Kenta

TURNET ETHINGE