## FIELD INSPECTION REPORT

D. t Cla	anation t	112/0020	District: MADHOBAN	r	
Date of Inspection . 3 12 20 -			1		
Division: THANSHARPOIR Length (km): 42391 Km  Name of the Road: NH 57 (gls) Bideshows Asstrant to Kothinga SH-52					
		MAINTENANCE	3054 (MR)		
	rogramme:	Wirthtta	Road Id No.: 31909808	3093	
Package No.:  Status of the Project:		Ongoing/Completed/Under Maintenance			
Work is a case of:		New Connectivity/Up gradation/ Maintenance			
Bunor Parameters to be checked					
	Pavement	(1) (1) (1) (1) (1) (1) (1) (1) (1) (1)			
a)	Road Junction condition			s/u	
b)	Condition of Surfacing			S/UV	
<u> </u>	Riding Quality			√S/U	
c)	Road Camber			<b>28/U</b>	
d) c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			✓Ycs/No	
n	Contraction Joints provided or not (CC Pavement)			√Ycs/No	
g)	Compaction of flank/slope & raincuts if any			√Yes/No	
124	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			✓S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			✓\$/SRI/U	
c)	Condition of railings/slab/approach for Bridges			_S/SRI/U	
3.	-Road Furniture				
a)	Whether sign stones/Pavem	√Yes/No			
46.5	Compliance History				
a)	Status of ATI	R's & any others		No	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

(Signature)

NAME: MD GYASUDDIM

DESIGNATION: (AE)