## FIELD INSPECTION REPORT

		FIELD INSPECTION	REPORT	
Dat	e of Inspection:	03.12.2020		Darbhanze
Division:		Darbhonga-1		
Name of Road:		Paghar to Khavra Sirua		2,80 KW
Sch	eme/Progrmme:	Maintenance	The STINE	
	kage No.	MR 3054	Doodlida	
Status of the Project:		Ongoing/Completed/ Under Maintenance		31909200834
Work is a case of:		New Connectivity/Up gradation/ Maintenance		
				enance
S No.	Parameters to be Checcked		Remarks	
1	Pavement			
a)	Road Junction condition			S/U S
b)	Condition of Surfacing			S/U S
c)	Riding Quality			S/U S S/U S
d)	Road Camber			
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement			S/U S Yes/No Zeo
f)	Contraction Joints provided or not (CC Pavement)			Yes/No Y
g)	Compaction of flank /slope & raincuts if any			Yes/No Y
2	Cross Drainage			Tes/No 9
a)	Condition of head walls in Hume pipe culverts including its painting			C/CDI/II
1-)				S/SRI/U S
b)	Condition of Abutment & Wing walls , Slabs in RCC culverts			S/SRI/U S
c)	Condition of railing /slabs/ approach for Bridges			S/SRI/U —
3	Road Furniture			
	Whethersign boards/informatory/cautionary Board / Km &			
	200m stones/ Pavement road markings are provided and			Yes/No No
	maintained			
3	Complianace History			
a)	Status of ATR's & a	ny others		No.
eral	l Rating:			
		Satisfactory (S)		
	Satisfactory but requires Improvement (SRI)			I) SRI
		Unsatisfactory (U)		

Name: Theeras Kumeer Designation: J.E Daher' Alus 311420 AE 3.12.2020 (Signature)