FIELD INSPECTION REPORT

Date	of Inspection : O	2/12/20	District: East char	mbaran
Divis	MOL	ihari	Length (km): 4.5 km	1
THE REAL PROPERTY.	ne/Programme:	MAINTENANCE	Harazbur	
	ige No.:	MAINTENANCE	Road Id No.:	
	of the Project:	Ongoing/Completed	/Under Maintenance	
Work	is a case of:	New Connectivity/U	p gradation/ Maintenance	-11
SI. No		Parameters to		ald)
1.	Pavement		Maria de la companya della companya	Remarks
a)	Road Junction condition			-
b)				S/U
	Condition of St			87U
c)	Riding Quality			S/U
d)	Road Camber		S/U	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			
f)		Contraction Joints provided or not (CC Pavement)		Yes/No A
g)	Compaction of flank/slope & raincuts if any		Yes/No N	
2.	Cross Drainage		if any	Yes/No
	THE RESERVE AND ADDRESS OF THE PARTY OF THE	The state of the s		
a)	Condition of hea	ad walls in Hume pipe	culverts including its painting	S/SRI/U
b)	Condition of Ab	utment & Wing walls,	Slab in RCC culverts	
c)	Condition of rail	ings/slab/approach for	Bridges	S/SRI/U N/
3.	Road Furniture	THE PERSON		S/SRI/U A
1)	Whether sign be stones/Pavement	oards/informatory/cau road markings are pro	tionary Board/km & 200m	/Yes/No
. (Compliance Hist	ory	The state of the s	140
THE RESERVE	Status of ATR's &	THE RESERVE OF THE PARTY OF THE	Application of the second	
	or miles a	c any others		

Overall Rating

Satisfactory (S)	
	2
Satisfactory but requires Improvement (SRI) Unsatisfactory (U)	-
Chisatisfactory (U)	_

175 m length of Road surface damaged due to flood-2000

HO3/120
(Signature)

NAME: pfran Ahmed

DESIGNATION: A-3