FIELD INSPECTION REPORT

Date of I	nspection: 0	3/12/2020	District: Madhe bura		
Division: Udakishangany Length (km): 5.800 K			<u>m</u>		
Name of		hausa to	Morsanda		
Scheme/	Programme:	MAINTENANCE		211	
Package			Road Id No.: 210048008	5//	
	the Project:	Ongoing/Completed	Munder Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance			Remarks		
Sl. No.	100	Parameters to	be checked	TCINE 4	
1	Pavement				
a)	Road Junction condition			S/U	
b)	Condition of Surfacing			S/U	
	Riding Quality			S/U	
	Road Camber			√s/U	
d) e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
	Contraction Joints provided or not (CC Pavement)			Yes/No	
f)	Compaction of flank/slope & raincuts if any			Yes/No	
g) 2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	14.6
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	1,
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				
4.	Compliance History				
a)	Status of ATR's & any others			No	

Overall Rating

Satisfactory (S)	の事が
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Remarks >> Length 100m damage due to Slovel - 2020

Att

NAME:

(Signature)

OH 12

Scanned with CamScanner