## FIELD INSPECTION REPORT

Division: Oak ablay &		District: Chebbina (Kasmery)	
		Length (km): 3,43	
Name of the Road:	ha to lakh	amaubur	
C. t /Dan manner	MAINTENANCE		
Package No.: MR-N	12019-20/13	Road Id No.: 1030140 2009	
Status of the Project:	Ongoing/Completed/Under Maintenance  New Connectivity/Up gradation/ Maintenance		
Work is a case of:	New Connectivity/	Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks -
1.	Pavement	國國軍團
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	
c)	Riding Quality	
d)	Road Camber	S/U "
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	
n	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	√S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
	Condition of railings/slab/approach for Bridges	S/SRI/U
c)	Rond Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating

Satisfactory (S)	S -	
Satisfactory but requires Improvement (SRI)	-	
Unsatisfactory (U)		

(Signature)

NAME: Birandra Kumer Single DESIGNATION: A. E. Chainpur