

Channel

## FIELD INSPECTION REPORT


Date of Inspection : - 03/12/20		District: Bhabhua (Kannur)	
Division : Bhabhua		Length (km): 8.27 km	
Name of the Road: Kuddi more PWD road to Rajabayas via Valani			
Scheme/Programme: MAINTENANCE			
Package No.: MR (3054) OH		Road Id No.: 10301402005	
Status of the Project: Ongoing/Completed/Under Maintenance ✓			
Work is a case of: New Connectivity/Up gradation/ Maintenance ✓			

Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition	✓ SU -
b)	Condition of Surfacing	SU ✓
c)	Riding Quality	✓ SU
d)	Road Camber	✓ SU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U - N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	x
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	x

  
 (Signature)

NAME: Shashi Bhushan Pathak

DESIGNATION: JE