

FIELD INSPECTION REPORT

Date of Inspection :		District: <i>East Champaran, Motihari</i>
Division : <i>WORKS Division Patnodaya</i>		Length (km): <i>4.300 K.M</i>
Name of the Road: <i>Cham Papur Main road To Betaura</i>		
Scheme/Programme: <i>MAINTENANCE</i>		<i>(OLD)</i>
Package No.:		Road Id No.:
Status of the Project:		Ongoing/Completed/Under Maintenance
Work is a case of:		New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Gross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓ S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	- N/A -

Overall Rating :

Satisfactory (S)	✓ S
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	-

Sd/-
31/12/20
S.F

Quil
08/12/20
A2

(Signature)