( Block - Tagdishpor)

## FIELD INSPECTION REPORT

Date	of Inspection: and	00
Divis	03/11/2004	
-	Chagalow. Blagalow	
Nami	A TALL	
	1 Carlo Carlo III	the state of the same of the same
Packs	me/Programme:   MAINTENANCE	
Status	Troup Ma	
SL. No	is a case of :   Ongoing /completed/Under Maintenance  D. Parameters   Parameters	
1	1. arement	Remarks
a)	Road Junction condition	
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
		S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Cpmpaction of flank/slope & raincuts if any	Yes/No
2	Cross Drainage	1,53/110
	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
) (0	Condition of Abutment & Wing Walls, Slab in RCC culverts	S/SRI/U
)	ondition of railings/slab/approach for Bridges	S/SRI/U
R	oad Furniture	2,0.11,0
la.	thathas size hands to form	
ste	hether sign boards/informatory/cautionary Board/km & 200m ones/Pavement road markings are provided and maintained	Yes/No
Co	mpliance History	a compe
Sta	itus of ATR's & any others	ИБ

Overall Rating: Work in hopess.

5
Approximation .

AME: Radha Raman Lingh

DESIGNATION: (Assistant Eigineur)

Scanned with CamScanner