FIELD INSPECTION REPORT

Block-Sultangey.

te of In	spection: 3.12.20 District: Bloggalpur.		
vision:	Bragerpor Length (Km): 2.02		
ame of	the Road: Pansalla Chowle to leumetha.		
cheme/	Programme: MAINTENANCE		
	No.: Group No - 10 Road Id No.: 20703202090.		
	the Project: Qngoing /completed/Under Maintenance		
Vork is a	a case of : New Connectivity/Up gradation/ Maintenance	emarks	
SL. No.	Parameters to be checked R		
1	Pavement	S/U	1
a)	Road Junction condition	S/U	1
b)	Condition of Surfacing		1
c)	Riding Quality	S/U	1
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
		Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Cpmpaction of flank/slope & raincuts if any		1
2	Cross Drainage		1
a)	Condition of head walls in Hume pipe culverts including its painting	s/sri/U	۱
	Condition of Abutment & Wing Walls, Slab in RCC culverts	S/SRI/U	4
b)	Condition of Abutment 2 Condition of railings/slab/approach for Bridges	S/SRI/U	+
c)		5.15	
3	Road Furniture	0	
a)	Whether sign boards/informatory/cautionary Board/km & 200n stones/Pavement road markings are provided and maintained	yes/No	
	Compliance History		
a)			
10 BOOK 100	and have whole been started yet.		
Overa	Il Rating: Work No.	· · · · · · · · · · · · · · · · · · ·	_

Satisfactory(S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory(U)

(Signature)

NAME: H.N. mahto.

r scharelby.