

FIELD INSPECTION REPORT

Date of inspection :	2.12.2020	District:	Siwan
Division :	R-W-D Mahataganj	Length (km):	4.725 Km
Name of the Road:	Bagaucha to Lerua		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of Bank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Rume pipe culverts including its painting	✓S/SR
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓S/SR
c)	Condition of roadways/slab/approach for Bridges	✓S/SR
3.	Road Furniture	
a)	Whether sign, board, informative/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	Compliance	
a)	Status of ATR's, etc., others	

Overall Rating

Satisfactory (S)	S
Satisfactory but requires improvement (SI)	—
Dissatisfactory (U)	—


2-12-2020
(Signature)

NAME: Sushil Kumar

DESIGNATION: J-E