FIELD INSPECTION REPORT

			District: Bhozpus	
eate of Inspection: 2-12-20			Length (km): 2-5	
ivision :	919	0	purgaethan to Harpur 191	ch and lach
Name of the		MAINTENANCE	MR-3054 (OL)	رد
Scheme/Pro	ogramme	DAUSE L	Road Id No.:	
Package No	Droiget:	Ongoing/Comple	ted/Under Maintenance	
Status of the Work is a		New Connectivity	y/Up gradation/ Maintenance MR-	3034(00)
AND DESCRIPTION OF THE PARTY OF	case or.		to be checked	Remarks
Sl. No.				4 1 1 2 1 1
TE TE TO THE TAIL	Pavement			S/U
a)	Road Junction condition			S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	Road Camber Whether free from defects such as visible cracks, exposed			
	1171 shor free	Yes/No-		
e)	aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			
2.	THE RESIDENCE OF THE PERSON WITH THE			S/SRI/U
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U N
	Condition of railings/slab/approach for Bridges			3/3/0/17
c)	Road Furniture			1 1 3
a)	Whether sign boards/informatory/cautionary Board/km & 200n stones/Pavement road markings are provided and maintained			Yes/No Se
4.	Compliance History			12年12年12年
E TOTAL PROPERTY.		TR's & any other		-

Overall Rating

	+
Satisfactory (S)	SRI
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME:

DESIGNATION:

अशोक कुमार मिश्रा मुख्य अभियंता-। ग्रामीण कार्य विभाग