## FIELD INSPECTION REPORT

ate of In	spection: 3/	12/2020 District: Samastet	248
)ivision :	RWD, Da	15; ug Sara' Length (km): 3.017 &	Thorst.
Vame of t	he Road: Ar	22/2/ DAS CAR 20 1 10 Char	17 04076
	10gramme.	Road Id No.:	and the second s
ackage		angoing/Completed/Under Maintenance	
	V	lew Connectivity/Up gradation/ Maintenance	
Down store to be checked		Remarks	
Sl. No.			
1.	Pavement 8/U		
a)	Road Junction condition		18/U
b)	Condition of Surfacing		√8/U
c)	Riding Quality		
d)	Road Camber		\8/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/NX
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No
2.	Cross Drainag		
	Condition of head walls in Hume pipe culverts including its painting S/SRI/U		
a)	Condition of Abutment & Wing walls, Slab in RCC culverts		- S/SRI/U
b)	Condition of railings/slab/approach for Bridges		- S/SRI/U
c)			
3.	Road Furnitu		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		
4.	Compliance History		THE STATE OF THE S
a)	Status of ATR's & any others		
117			
Overa	Il Rating :	Satisfactory (S)	5
		Satisfactory but requires Improvement (SRI)	
		Unsatisfactory (U)	

NAME: Ben Chandles Bupls
DESIGNATION: ASST Engineer.